

ERRATA #:	PER2015001	PER ISSUE DATE:	May 12 2015				
ERRATA TITLE:							
ACC-01-1202 Cable lock position change							
REVISION:	1.0	CUSTOMER CONTACT:	sales@ptgrey.com				
AFFECTED PART NUMBER(S):							
<table border="1"> <thead> <tr> <th>Part Number</th> <th>Description</th> </tr> </thead> <tbody> <tr> <td>ACC-01-1202</td> <td>Generic USB 3.0 PCI Express 2.0 x1 host adapter card, FL1100 chipset, 4-port</td> </tr> </tbody> </table>				Part Number	Description	ACC-01-1202	Generic USB 3.0 PCI Express 2.0 x1 host adapter card, FL1100 chipset, 4-port
Part Number	Description						
ACC-01-1202	Generic USB 3.0 PCI Express 2.0 x1 host adapter card, FL1100 chipset, 4-port						
SYMPTOMS:							
The screw locking configuration on ACC-01-1202 has been changed. Refer to the table below for details.							
<table border="1"> <thead> <tr> <th>Before</th> <th>After</th> </tr> </thead> <tbody> <tr> <td> </td> <td> </td> </tr> </tbody> </table>		Before	After				
Before	After						
OCCURRENCES:							
Units with batch codes beginning with B1014 (October 2014) or higher will reflect this change.							
CAUSE:							
This change was initiated by the supplier.							
RESOLUTION:							
After initial discovery of symptoms, Point Grey launched a Corrective Action investigation. As a result, Point Grey will be updating our product documentation to refer to the new configuration.							
CUSTOMER ACTION REQUIRED							
Customers can contact sales@ptgrey.com if they are interested in replacement brackets that use the previous layout.							

Document Number:	PER2015001
Revision Number:	1.0
Revision Date:	12-May-15
Document Availability:	Public